

# WPZ 80-150

## SOLID COMPOUND APPLICATORS SPARE PARTS LIST

01	Foot to frame
02	Cylinder cover
03	Clamping attachment
04	Crosshead
05	Fork piece
06	Hinge
07	Clamping jaw
08	Clamping plate + cylinder
09	Pilot finger (2)
10	Clamping piston*
11	Lifting cylinder (2)
12	Piston (2)
13	Guide shaft (2)
14	Clamping cylinder compl.
15	Regulation rod
16	Distance rod
17	Distance rod
18	Feed regulator
19	Bushing (2)
20	Limit stop
21	Clamping piston**
22	Bushing (2)
23	Connection piece
24	Connection piece
25	Wheel shaft
26	Hose stem
27	Screw fitting (2)
28	Screw (2)
29	3-way-valve
30	Hose stem
31	Seeger circlip ring (4)
32	Seeger circlip ring
33	Rubber dirt protector
34	O-Ring (3)
34A	Piston sealing ring for Clamping cylinder pos.14
35	O-Ring (2)
36	Stripper (4)
37	Connection hose
38	Connection hose
39	Cup seal (4)
40	Nipple for clamping cylinder
41	Sealing ring (4)
42	Hollow-core screw (2)
43	Hollow-core screw
44	Straining screw (4)
45	Locking screw with collar (2)
46	Hexagon socket screw (2)
47	Nut (2)

